

# REDI-Sensor™

## Tips & Tricks



REDI-Sensor™ uses advanced patented technology and is compatible with many high line and auto-learn systems.

- It is important to update TPMS scan tools regularly to have access to latest vehicle relearn coverage.
- For many vehicles, the IDs must be written to the vehicle via OBD-II using a properly formatted TPMS scan tool.
- If an error occurs during installation or the relearn process, the REDI-Sensor™ may need to be unlocked.

This function can be found on the compatible scan tools shown below:



### Relearn challenges may occur if

- The wrong make, model, year, sub-model or trim level is selected in the tool.
- The relearn is not performed in entirety.
- The vehicle is prematurely driven.
- A tool with incompatible software is used.



### Continental Automotive Systems

For more information contact your REDI-Sensor Sales Manager  
[www.redi-sensor.com](http://www.redi-sensor.com) | [salesupport-us@continental.com](mailto:salesupport-us@continental.com)  
Tech Support: 800-265-1818